# MARINER 2 WEST GOSHEN TOWNSHIP

Accufacts Inc.

1/11/17 Presentation to Township Council

### ACCUFACTS INC.

- Assist decision makers on pipeline matters
  - Provides neutral, critical factual Information
  - Based on wealth of operational, design, siting, regulatory, emergency response, and investigation experience
- Some recent public reports
  - Review of U.S. Army Corp of Engineers EA for Earthjustice/Sioux
  - Mississippi & Nevada Public Service Commissions
  - > Citizens
  - Many state and local governments
- Respect sensitive information <u>not</u> always public

## ACCUFACTS 3/6/15 REPORT ON ME1

- 8-inch existing liquid mainline converted/reversed to HVL
- Hydrotesting protocols for at-risk vintage ERW meet Advisory Bulletin and Accufacts extensive experience for integrity
  - No mainline hydrotest failures, indicating quality vintage pipe
- Boot Road PS appropriate
  - Detailed analysis of pump station piping and instrument diagrams (P&Id's)
  - Flare installation prudent
- Release detection and remote/automatic control reviewed in detail
- Emphasized importance of ERP and Control Room Contact
- Concluded ME1 meets and exceeds important technical approaches for prudent HVL operation



## ACCUFACTS 8/1/16 REPORT ON ME2

- New 20-inch ~ 1 mile in Township
- ▶ High MAOP
- No pump station in Township
- Pipeline installed via two horizontal directional drills (HDDs) in/near ME1
  - Arc very deep under Township ROWs
  - Interactions with Township and other infrastructure critical through lifecycle
- Install above ground remotely operated valve within Township between HDDs
- Concluded ME2 incorporates additional safety measures for prudent safety

### CONCLUSIONS ON ME2

- Understand citizen concerns
- Avoid clearly false or misleading statements not based on facts
- ➤ ME2 exceeds pipeline safety regulations in many prudent areas
- First responders and township representatives are not in charge during pipeline release emergencies
  - Operator to "maintain liaison" required in federal pipeline safety regulation
  - > There is a handoff time

## KEY ISSUE OFTEN MISUNDERSTOOD

- Pipeline Safety and Pipeline Siting Two Very Different Regulatory Processes
  - > For liquid pipelines, states can have additional requirements
    - Few states have additional considerations
      - Pennsylvania apparently doesn't